

TRUESDAIL LABORATORIES, INC.

3337 MICHELSON DRIVE, SUITE CN 750, IRVINE, CA 92612

Certified Product Listing

For:

Drinking Water System Components - Health Effects

Company:

General Rubber Corporation 2201 E Ganley Rd Tucson, Arizona 85706, United States

Plant Location:

Tucson, Arizona, United States

Standards:

NSF/ANSI/CAN 61 - 2020 NSF/ANSI 372 - 2016

Certificate:

Issued Date: 12/21/2020

Material/Product:

Expansion Joint

Contact Temperature:

23 ± 2°C

Models:

Series 1100 Rubber Expansion Joint (2"-96" ID)



